



## Firmware Update (version 8.05) for Certain Pioneer In-Dash AV Receivers

February 8, 2018

**Dear Valued Pioneer Customer:**

We would like to inform you of the availability of a firmware update (version **8.05** for the current lineup of Pioneer In-Dash AV Receivers.) **This firmware update is only for the following Pioneer In-Dash AV Receivers sold in Cambodia, Indonesia, Laos, Malaysia, Philippines, Singapore, Sri Lanka, Thailand and Vietnam.**

**Warning:** Installation on any other product could cause irreversible damage.

This firmware update (version **8.05**) contains the following improvements:

- **Fix a problem that the H/U skips a next music in case of iPod source when "Short Playback Mode" of MIXTRAX settings is on.**
- **Fix a problem that the artwork does not changed sometimes when iPod source.**
- **Fix a problem that the voice recognition button of wired remote does not work.**

**In order to perform this update, the following items are needed:**

- Pioneer In-Dash AV Receiver: AVH-X595BT
- Blank USB storage device (no files), 2 GB or larger in capacity, formatted to FAT32

Steps to install the firmware are attached. Installation of the update should take no more than ten minutes to complete.

**How to Obtain the Free Firmware Update:**

1. Download the firmware update files to a computer from the Pioneer website: [www.pioneer.com.sg/sg/support/service/index.html](http://www.pioneer.com.sg/sg/support/service/index.html)
2. Transfer the files to the USB storage device for insertion into the Pioneer In-Dash AV Receiver.

### Questions

If you have any questions, please contact the nearest Pioneer Customer Service at your country. You can refer to [www.pioneer.com.sg/sg/support/service/index.html](http://www.pioneer.com.sg/sg/support/service/index.html) for more information.

Sincerely,

Pioneer Electronics AsiaCentre Pte. Ltd.