



Firmware Update (version 8.22 for Certain Pioneer In-Dash AV Receivers)

February 8, 2018

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update (version **8.22**) for the current lineup of Pioneer In-Dash AV Receivers. **This firmware update is only for the following Pioneer In-Dash AV Receivers sold in Cambodia, Indonesia, Laos, Malaysia, Philippines, Singapore, Sri Lanka, Thailand and Vietnam.**

Warning: Installation on any other product could cause irreversible damage.

This firmware update (version **8.22**) contains the following improvements:

- **Fix a problem that the H/U skips a next music in case of iPod source when "Short Playback Mode" of MIXTRAX settings is on.**
- **Fix a problem that the artwork does not changed sometimes when iPod source.**
- **Fix a problem that the voice recognition button of wired remote does not work.**

In order to perform this update, the following items are needed:

- Pioneer In-Dash AV Receiver: AVH-X1850DVD, AVH-X2850BT, AVH-X4850DVD, AVH-X5850BT, AVH-X6850DVD, and AVH-X7850BT
- Blank USB storage device (no files), 2 GB or larger in capacity, formatted to FAT32

Steps to install the firmware are attached. Installation of the update should take no more than ten minutes to complete.

How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website:
www.pioneer.com.sg/sq/support/service/index.html
2. Transfer the files to the USB storage device for insertion into the Pioneer In-Dash AV Receiver.

Questions

If you have any questions, please contact the nearest Pioneer Customer Service at your country. You can refer to www.pioneer.com.sg/sq/support/service/index.html for more information.

Sincerely,

Pioneer Electronics AsiaCentre Pte. Ltd.